

## The right speed for the application



Choose the right speed for your application

TO CONVERT SURFACE FEET PER MINUTE (SFM) TO RPM:

$$\text{SFM} = \frac{\text{DIAMETER} \times \text{RPM}}{3.82}$$

