

V - Not Available Page 1 of 2

Surface Tech	ALTER MATERIAL SAFETY DATA SHEET ace Technologies L-98E			
Section 6 - Toxicological Data				
Acute exposure Chronic exposu Exposure limits Carcinogenicity No	<b>ITE effects:</b> Serious damage to <b>(TLV/TWA):</b> N/A	n, ingestion. nd skin, possibilities of headaches health by prolonged exposure thro <u>Reproductive toxicity</u> No		ation. <u>Synergistic effects</u> No
Section 7 - Preventive Measures				
Protective equip Handling proces Waste disposal Leak/spill proces Storage require Engineering con Handling equips Special shipping	dures:Keep awaymethods:Eliminate wedures:Eliminate soments:Store underntrols:Sufficient voment:N/Av		deral regulations.	
Section 8 - First Aid Measures				
Skin contact:	Flush with water until substance is washed away.			
Eye contact:	Flush the eye with water for at least 15 minutes, seek medical attention.			
Inhalation:	Remove patient to fresh air. Seek medical attention.			
Ingestion:	Seek medical attention			
Other:				
Section 9 - Preparation of MSDS				
Prepared by: Telephone: Date:	Chemical Tools Manager 860-298-1100 May 1, 2008			
This data is offered in good faith as typical values and not as a product specification. No warranty, either express or implied is hereby made. The recommended industrial hygiene and safe handling procedures are believed to bee generally applicable. However, each user should review these recommendations in the specific context of the intended use and determine whether they are appropriate.				

N/A - Not Applicable

N/Av - Not Available Page 2 of 2