


MATERIAL SAFETY DATA SHEET L-110E



Section 1 - Product Identification

J. Walter Inc. 810 Day Hill Road Windsor, CT 06095

Trade name: Product name: Order no.: WHMIS Classification: Controlled under WHMIS: **Spatter Block PRO** Weld spatter release 53F-267, 53F-268 Non-hazardous No

LD₅₀RAT

Emergency: Infotrac 800-535-5053

Section 2 - Hazardous Ingredients

Ingredients

CAS Number % by Weight

No hazardous substances to declare.

Section 3 - Physical / Chemical Characteristics

Physical state: Liquid 8,5 pH: Specific gravity: 1.019 g/ml @ 68°F Evaporation rate: N/Av

Boiling point: Vapor pressure: VOC g/l:

Odor & appearance: Blue, transparent, pleasant odor 210°F N/Av N/Av

Odor threshold: None 32°F Freezing point: Vapor density: N/Av Water solubility: Soluble

LC₅₀RAT

Section 4 - Fire & Explosion Hazard

Flammability: No Conditions: None Flashpoint: N/A

Flammable limits (%): Upper: N/A Lower: N/A

Auto ignition temperature: N/A

Extinguishing media: N/A Hazardous combustion products: None Sensitivity to mechanical impact or static discharge: No

Section 5 - Reactivity Data

Conditions: None Chemical stability: Yes Reactivity conditions: None Incompatible substances: Strong acids Hazardous decomposition products: None

N/A - Not Applicable

N/Av - Not Available Page 1 of 2

WALTER Surface Technologies MATERIAL SAFETY DATA SHEET L-110E				
		Section 6 - Toxico	logical Data	
Acute exposure Chronic exposu Exposure limits <u>Carcinogenicity</u> No	re effects: None (TLV/TWA): N/Av	ngestion. hay cause slight irritation. <u>Reproductive toxicity</u> No	<u>Teratogenicity</u> No	<u>Synergistic effects</u> No
		Section 7 - Prevent	ive Measures	
Protective equipment: Handling procedures: Waste disposal methods: Leak/spill procedures: Storage requirements: Engineering controls: Handling equipment: Special shipping information:		Eyewear None Dispose as per municipal, state and federal regulations. Flush with water. Store upright. Protect from freezing. None None Ship upright. Protect from freezing.		
		Section 8 - First A	id Measures	
Skin contact:Rinse with plenty of fresh water.Eye contact:Flush with plenty of fresh water.Inhalation:N/AIngestion:Do not induce vomiting.Other:N/A				
		Section 9 - Prepara	tion of MSDS	
Prepared by: Telephone: Date:	Chemical Tool Mana 860-298-1100 December 10, 2008	ager		
recommended ind	ustrial hygiene and safe ha in the specific context of t		e generally applicable. H	xpress or implied is hereby made. The lowever, each user should review these N/Av - Not Available

N/Av - Not Available Page 2 of 2